A visitor to your Web site has filled out the form located at: <a href="http://www.w4ghs.org/Tsunami\_After\_Action\_Review.html">http://www.w4ghs.org/Tsunami\_After\_Action\_Review.html</a>

Expectations for the SET	To exchange messages with winlink using forms.
What Occured	I could initiate a message using the ICS 213 form but I could not reply to one received using the ics form.
What Went Well and Why	VHF voice to Wytheville 146.175 was much clearer than to the W4GHS repeater today. Winlink worked well. I used both KA4EMH-10 & W4GHS-10.
Improving Operation and How	When HF moved to 60M I became unable to communicate - equipment. The radios I had available, the Floyd EOC's Kenwood TS-2000, and my Elecraft K2 & Yaesu FT-747, were not able to transmit on 60M.
Your Call	n3mdg
Your Location	Willis, Va
Other Calls at Your Location	KM4UDB
Messages Sent	9
Messages Received	5

-----

Regards,
The Homestead Team